

**Work Order ID 61996**

Page 1

Wednesday, September 15, 2010 9:52:35 AM

Item ID: D3566-13

Accept



Setup Start



Revision ID:

Item Name: Gasket

Stop



Start Date: 9/14/2010 Start Qty: 12.00



Cust Item ID:

Required Date: 9/21/2010 Req'd Qty: 12.00



Customer:

Reference:

Approvals: Process Plan: *JH*Date: *10-9-15* Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3566	Rev C

100

0.00



FLOW WATER JET

Waterjet

Memo

0.00

*B10-9-21*

FLOW CNC Waterjet

1-Cut as per Dwg D3566  Dwg Rev: *C*  Prog Rev: *C*  2-  
Deburr if necessary*26*

110

QC2- Inspect parts off machine FAI/FAIB

0.00



QC

Memo

0.00

*B10-9-21*

Quality Control

120

QC8- Inspect parts - second check

0.00



QC

Memo

0.00

*5.00/22**Count**726*

Quality Control

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

**Work Order ID 61996**

Page 2

Wednesday, September 15, 2010 9:52:35 AM

Item ID: D3566-13

Accept



Setup Start



Revision ID:

Item Name: Gasket

Stop



Start Date: 9/14/2010 Start Qty: 12.00



Cust Item ID:

Required Date: 9/21/2010 Req'd Qty: 12.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

130



Packaging

Identify as per dwg &amp; Stock Location:

0.00

10/9/2010 (200)

Packaging

140



QC

QC21- Final Inspection - Work Order Release

0.00

Quality Control

Memo

0.00

10/9/2300

MEP 10-9-23

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

# Picklist Print

Wednesday, September 15, 2010 9:52:40 AM

Page 1

Work Order ID: 61996



Parent Item: D3566-13



Parent Item Name: Gasket

Start Date: 9/14/2010

Required Date: 9/21/2010

Start Qty: 12.00

Required Qty: 12.00

Comments: IPP Rev:A New Issue 07-03-08 ec  
IPP Rev:B Added Drain Holes 07-07-09 JLM  
IPP Rev:C As per Rev C 07-09-09 JLM Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MNEO60S.063 		Purchased		No		100	sf	477.6133	0.195	2.463158	S.1	18 10-9-21	

NEOPRENE SHEET 0.063

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
MAT	372.3602	
114691	105.9602	
115500	266.4	115500
MAT052	105.2531	
114176	105.2531	

26

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	W1994
Description: Gasket	Part Number:	D3566-13
Inspection Dwg: D3566	Rev: C	Page 1 of 1

# FIRST ARTICLE INSPECTION CHECKLIST

## X First Article      Prototype

Measured by: <u>BS</u>	Audited by: <u>S</u>	Prototype Approval: N/A
Date: 10-9-21	Date: 10/09/22	Date: N/A

Rev	Date	Change	Revised by	Approved
A	07.04.20	New Issue	KJ/JLM	
B	07.07.18	Dimensions updated per Dwg Rev. B	KJ/JLM	
C	08.09.04	Dwg Rev updated	KJ/DD	DD


W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries